



Safety Review

- ALWAYS wear your safety goggles/glasses
- ALWAYS watch your surroundings
- Check any MSDS sheets provided for what you are working with
- If you ever get hurt, tell someone
- Don't forget to put up long hair when you are working

- If someone gets hurt, the first thing to do is get help
- NO HORSEPLAY
- Make sure you know where safety items are located such as the first aid kit and eye wash
- Always read warning labels
- Don't operate machines when you are alone

Soldering Iron

- When you're done with the iron, place it back in its stand
- On average, soldering guns can get up to 400 degrees
- Never touch the tip of the iron
- Do not inhale the smoke that is produced

Miter Saw

- Let the blade stop completely before raising the arm
- Do not force the saw blade through things
- Tuck in loose jewelry or clothing when working
- Never use dull or damaged blades
- Never leave the saw running unattended

Drill Press

- The harder the material being cut, the slower the cutting speed needed
- Don't wear gloves or anything that could get your hands caught in the machine
- Do not exceed recommended speeds
- Clean off machines with a broom or vacuum

Band Saw

- Is used to cut curves
- Tuck back all loose items
- Pay attention to your work, not other things
- Keep bystanders away while you're working
- Never use your thumbs to push a small item towards the blade